## Approved For Release 2000/9901 : CIA-RDP81B00878R001400030096-4

SAPC-12236 Copy 2 of 6

10 January 1957

## Burt:

Attached is a copy of a memo to me from Jim summarizing technical problems encountered in the use of the Read-Out equipment.

Would you review the stated technical problem and initiate corrective action on existing units and on future production units, as indicated in paragraph B of Jim's memo.

In the event that any particular "fix" involves a major effort would you please communicate with me prior to initiating action. I have in mind major redesign or similar expensive corrective action.

Thanks.

George

## Attachment

25X1A SA/PC/DCI/Expr (1/10/57)

Distribution:
 Orig = Burt
 Cy 2 - A-101
 3 - ESO (
25X1A 4 - Commo
 5 - Ops (
 6 - Chrono

DOBUMENT NO.

HIS CHARGE IN STARS. X

CHARGE CONTROL TO S & C 2012

HEAT CALLED CONTROL TO S & C 2012

ACTURE IN 109

DATE: 1/1/22 ACTURE 2012 CO 4540

LLI

	NTRAL INTELLIGENCE ACTIONS		
TO NAME	AND ADDRESS	INITIALS	DATE
1 Proved	Duester		
2 0 0	.: 0:		
3 0 3	7		
BYP	V		
4			
5	,	1	
6			
ACTION	DIRECT REPLY	PREPARE	DEDLY
	DISPATCH		NDATION
APPROVAL	DIST ATOM	I ILLOOMINE	
COMMENT	FILE	RETURN	
COMMENT CONCURRENCE Remarks:	FILE INFORMATION	RETURN SIGNATUR	E
COMMENT CONCURRENCE Remarks:	FILE	RETURN SIGNATUR	E
COMMENT CONCURRENCE Remarks:	FILE INFORMATION	RETURN SIGNATUR	E
COMMENT CONCURRENCE Remarks:	FILE INFORMATION  Ty sent to  Correct,	RETURN SIGNATUR  But  aut  continues  contin	E

25X

1 APR 55 23/ Replaces Form 30-4 which may be used.